


System condition after functional test "test-funkcjonalny" of 14.10.2019, 12:05:00



Checked filters

Vertex	Group	Status
<ul style="list-style-type: none"> [27] VERTEX_0055002934375117 	<ul style="list-style-type: none"> [27] Test group 1 [0] Test group 2 [0] Test group 3 [0] Test group 4 [0] Test group 5 [0] Test group 6 [0] Test group 7 [0] Test group 8 [0] Ungrouped 	<ul style="list-style-type: none"> [27] OK [0] Out of date [0] No communication [0] Circuit failure [0] Battery duration failure [0] Battery failure [0] Emergency lamp failure [0] Not tested [0] Battery not fully charged [0] Functional test max delay exceeded [0] Duration test max delay exceeded [0] Functional test failed [0] Duration test failed

Name (Serial number)	Test group	Vertex name (UID)	Status	Details	Date
4 C korytarz k/pok 419 (10008503)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
3 C korytarz k/windy (100069F4)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
4 C korytarz k/pok 415 (1000850C)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
4 C spocznik klatka schodowa (10008802)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
4 C korytarz k/pok 411 (10008501)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
C 4 klatka schodowa winda (100084FE)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
4 C korytarz k/windy (10008015)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
3 C korytarz k/pok. 324 (10008800)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
3 C korytarz k/pok. 304 (10008510)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
3 C korytarz k/pok. 312 (10008804)	1	VERTEX_0055002934375117	OK		2019-10-14 12:05:00

Name (Serial number)	Test group	Vertex name (UID)	Status	Details	Date
		(55002934375117)			Tested
3 C korytarz k/pok. 307 (10008500)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
VERTEX 1 (10002F1D)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
3 C klatka schodowa winda (10008502)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
VERTEX 2 (100087B3)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
4 C korytarz k/pok.404 (10002F63)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
4 C korytarz k/pok. 407 (1000850E)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
3 C korytarz k/pok 309 (10008807)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
4 C korytarz k/pok. 439 (10008803)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
4 C korytarz k/pok 409 (10008809)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
3 C spocznik kl. schodowa (10002F43)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
4 C korytarz k/pok. 438 (10008507)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
4 C spocznik klatka sch. sciana (10002F2E)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
3 C korytarz k/pok 303 (100069F5)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
VERTEX 4 (10008805)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
VERTEX 3 (10008A3C)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
3 C korytarz k/pok 319 (1000880B)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested
3 C korytarz k/pok 302 (1000850D)	1	VERTEX_0055002934375117 (55002934375117)	OK		2019-10-14 12:05:00 Tested